



EDGEWOOD REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	EDGEWOOD RECREATION CENTER	5/24/2016	WS- 003793	Utility	Ground Floor	Exterior entry room (mechanical) adjacent to field (water source)	WT-042916-3810- A	2.6	WT-042916-3810- B	1				
2	EDGEWOOD RECREATION CENTER	5/24/2016	WS- 003794	Cooler	1	In hallway adjacent to main office suite	WT-042916-3811- A	1.4	WT-042916-3811- B	< 1				
3	EDGEWOOD RECREATION CENTER	5/24/2016	WS- 003795	Kitchen	1	In kitchen fridge (ice maker)	WT-042916-3812- A	< 1	WT-042916-3812- B	< 1				
4	EDGEWOOD RECREATION CENTER	5/24/2016	WS- 003796	Kitchen	1	In kitchen	WT-042916-3813- A	1.3	WT-042916-3813- B	< 1				
5	EDGEWOOD RECREATION CENTER	5/24/2016	WS- 003797	Fountain	Ground Floor	In exterior adjacent to AC unit	WT-042916-3814- A	< 1	WT-042916-3814- B	< 1				
6	EDGEWOOD RECREATION CENTER	5/24/2016	WS- 003798	Fountain	Ground Floor	In exterior adjacent to AC unit	WT-042916-3815- A	< 1	WT-042916-3815- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.